RNAV (GPS) Z RWY 26L

MIAMI INTL (MIA)

WAAS	APP CRS	Rwy Idg	10506
CH 81905	272°	TDZE	8
W26A		Apt Elev	8

V For inoperative MALSR, increase LPV all Cats visibility to RVR 5000 and LNAV/VNAV all Cats visibility to 1½. DME/DME RNP-0.3 NA. For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -15°C (5°F) or above 48°C (118°F).

W

MALSF

MISSED APPROACH: Climb to 2000 direct LAWNN and via 345° track to BRBRA and hold.

ATIS	MIAMI APP CON	MIAMI TOWER	GND CON	CLNC DEL
119.15	124.85 322.3	118.3 256.9	121.8 (8L/8R/12/26L/26R) 127.5 (9/27/30) 348.6	135.35

MISSED APCH FIX

4 NM 156° 336° BRBRA

HILEY 3000 156° (20.9)

(IAF) MANTY 3000 233° (12.2)

EMBRA 3.5 NM to RW26L

(FAF) AGLER 272° 1600 273° (4.4)

BASHO 3000 273° (5.9)

(IF) ZILBI

MSA RW26L 25 NM 2900

345° LAWNN

RW26L

3000 335° (28.9) (IAF) FLIPR

ELEV 8 D

TDZE 8

272° to RW26L

8600 X 150

10506 X 200

9354 X 150

13000 X 150

TDZ/CL Rwy 8R
MIRL Rwy 8L-26R
REIL Rwys 8L and 26R
HIRL all Rwys

2000 LAWNN Trk 345° BRBRA

Procedure VGSI and RNAV glidepath not coincident. Turn NA

* LNAV only.

* 1.5 NM to RW26L

EMBRA 3.5 NM to RW26L 1600 272° 1180*

AGLER 273° 1600

BASHO 273° 3000

ZILBI 3000

GS 3.00° TCH 58

1.5 2 1.3 NM 4.4 NM 5.9 NM

CATEGORY	A	B	C	D
LPV DA	325/24 317 (400-½)			
LNAV/VNAV DA	450/50 442 (500-1)			
LNAV MDA	560/24 552 (600-½)		560/50 552 (600-1)	560/60 552 (600-1¼)

SE-3, 11 MAR 2010 to 08 APR 2010