


ATIS 120.775
 HENDERSON TOWER ★
 125.1
 GND CON
 127.8

35°59.0'N



JANUARY 2005
 ANNUAL RATE OF CHANGE
 0.1°W

RWY 17L-35R
 S30, D30
 RWY 17R-35L
 S30, D60

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.
READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

115°08.5'W 115°08.0'W 115°07.5'W

SW-4, 19 NOV 2009 to 17 DEC 2009

SW-4, 19 NOV 2009 to 17 DEC 2009